



unrivaled slice face stability

Hallmark Floors



cut from a veneer block
-allows wood to be pressure steamed for optimum stability



pressurized steaming (90/100F)
- for less stress = stability



vertically cut
- high end process for a stable cleaner, 2mm veneer

Others

cut from a log
- higher possibility for stress

boiling (212°F minimum)
- higher temperature weakens fibers

horizontal cut
- older process
- sliced veneer production



2360 S. Archibald Ave.
Ontario, CA 91761
888.551.0888 t
909.947.7776 f
www.hallmarkfloors.com